



	Measurements
Α	Distance Between Handle Holes
В	Handle Length
с	Distance Between Handle Holes To The Side
D	Distance Between Handle Holes To The Bottom
F	Min/Max Walk-In Width
G	Min/Max Shower Door Width Max Out Of Plumb Adjustment: 3/16"
н	Shower Door Height
C	Walk Through Opening Height








	Measurements
Α	Distance Between Handle Holes
В	Handle Length
с	Distance Between Handle Holes To The Side
D	Distance Between Handle Holes To The Bottom
F	Min/Max Walk-In Width
G	Min/Max Shower Door Width Max Out Of Plumb Adjustment: 3/16"
н	Shower Door Height
C	Walk Through Opening Height









	Measurements
Α	Distance Between Handle Holes
в	Handle Length
с	Distance Between Handle Holes To The Side
D	Distance Between Handle Holes To The Bottom
F	Min/Max Walk-In Width
G	Min/Max Shower Door Width Max Out Of Plumb Adjustment: 3/16"
н	Shower Door Height
C	Walk Through Opening Height













	Measurements
Α	Distance Between Handle Holes
В	Handle Length
с	Distance Between Handle Holes To The Side
D	Distance Between Handle Holes To The Bottom
F	Min/Max Walk-In Width
G	Min/Max Shower Door Width Max Out Of Plumb Adjustment: 3/16"
н	Shower Door Height
J	Walk Through Opening Height

