
DIMENSIONS



	Measurements
Α	Distance Between Handle Holes
В	Handle Length
С	Distance Between Handle Holes To The Side
D	Distance Between Handle Holes To The Bottom
F	Min/Max Walk-In Width
G	Min/Max Shower Door Width Max Out Of Plumb Adjustment: 3/16"
н	Shower Door Height
J	Walk Through Opening Height




Measurements provided are in mm and inches.





	Measurements
Α	Distance Between Handle Holes
В	Handle Length
С	Distance Between Handle Holes To The Side
D	Distance Between Handle Holes To The Bottom
F	Min/Max Walk-In Width
G	Min/Max Shower Door Width Max Out Of Plumb Adjustment: 3/16"
н	Shower Door Height
J	Walk Through Opening Height




Measurements provided are in mm and inches.

DIMENSIONS



	Measurements
A	Distance Between Handle Holes
В	Handle Length
С	Distance Between Handle Holes To The Side
D	Distance Between Handle Holes To The Bottom
F	Min/Max Walk-In Width
G	Min/Max Shower Door Width Max Out Of Plumb Adjustment: 3/16"
н	Shower Door Height
J	Walk Through Opening Height



Measurements provided are in mm and inches.







DIMENSIONS



Measurements		
A	Distance Between Handle Holes	
В	Handle Length	
С	Distance Between Handle Holes To The Side	
D	Distance Between Handle Holes To The Bottom	
F	Min/Max Walk-In Width	
G	Min/Max Shower Door Width Max Out Of Plumb Adjustment: 3/16"	
н	Shower Door Height	
J	Walk Through Opening Height	





Measurements provided are in mm and inches.

