



	Measurements
Α	Distance Between Handle Holes
В	Handle Length
с	Distance Between Handle Holes To The Side
D	Distance Between Handle Holes To The Bottom
F	Min/Max Walk-In Width
G	Min/Max Shower Door Width Max Out Of Plumb Adjustment: 3/8"
н	Shower Door Height
C	Walk Through Opening Height







Measurements		
Α	Distance Between Handle Holes	
В	Handle Length	
с	Distance Between Handle Holes To The Side	
D	Distance Between Handle Holes To The Bottom	
F	Min/Max Walk-In Width	
G	Min/Max Shower Door Width Max Out Of Plumb Adjustment: 3/8"	
н	Shower Door Height	
J	Walk Through Opening Height	










	Measurements
Α	Distance Between Handle Holes
в	Handle Length
с	Distance Between Handle Holes To The Side
D	Distance Between Handle Holes To The Bottom
F	Min/Max Walk-In Width
G	Min/Max Shower Door Width Max Out Of Plumb Adjustment: 3/8"
н	Shower Door Height
J	Walk Through Opening Height









Measurements	
Α	Distance Between Handle Holes
В	Handle Length
с	Distance Between Handle Holes To The Side
D	Distance Between Handle Holes To The Bottom
F	Min/Max Walk-In Width
G	Min/Max Shower Door Width Max Out Of Plumb Adjustment: 3/8"
н	Shower Door Height
J	Walk Through Opening Height

