
DIMENSIONS



	Measurements
Α	Distance Between Handle Holes
В	Handle Length
с	Distance Between Handle Holes To The Side
D	Distance Between Handle Holes To The Bottom
F	Door Opening
G	Min/Max Shower Door Width Max Out Of Plumb Adjustment:1 3/8"
н	Shower Door Height
C	Walk Through Opening Height




Measurements provided are in mm and inches.



DIMENSIONS



	Measurements
Α	Distance Between Handle Holes
В	Handle Length
с	Distance Between Handle Holes To The Side
D	Distance Between Handle Holes To The Bottom
F	Door Opening
G	Min/Max Shower Door Width Max Out Of Plumb Adjustment:1 3/8"
н	Shower Door Height
J	Walk Through Opening Height



Measurements provided are in mm and inches.





DIMENSIONS





	Measurements
Α	Distance Between Handle Holes
В	Handle Length
с	Distance Between Handle Holes To The Side
D	Distance Between Handle Holes To The Bottom
F	Door Opening
G	Min/Max Shower Door Width Max Out Of Plumb Adjustment:1 3/8"
н	Shower Door Height
J	Walk Through Opening Height





Measurements provided are in mm and inches.