
DIMENSIONS




	Measurements
Α	Distance Between Handle Holes
в	Handle Length
с	Distance Between Handle Holes To The Side
D	Distance Between Handle Holes To The Bottom
F	Min/Max Walk-In Width
G	Min/Max Shower Door Width
н	Shower Door Height
C	Walk Through Opening Height





\sim
Streamline


	Measurements
Α	Distance Between Handle Holes
В	Handle Length
С	Distance Between Handle Holes To The Side
D	Distance Between Handle Holes To The Bottom
F	Min/Max Walk-In Width
G	Min/Max Shower Door Width
н	Shower Door Height
C	Walk Through Opening Height



DIMENSIONS



	Measurements
Α	Distance Between Handle Holes
В	Handle Length
с	Distance Between Handle Holes To The Side
D	Distance Between Handle Holes To The Bottom
F	Min/Max Walk-In Width
G	Min/Max Shower Door Width
н	Shower Door Height
C	Walk Through Opening Height







	Measurements
Α	Distance Between Handle Holes
В	Handle Length
с	Distance Between Handle Holes To The Side
D	Distance Between Handle Holes To The Bottom
F	Min/Max Walk-In Width
G	Min/Max Shower Door Width
н	Shower Door Height
J	Walk Through Opening Height

